

## Office of the Chief Fire Officer, Bengaluru-East, Karnataka Fire & Emergency Services, No. 04, Commissariat Road, Bengaluru-560 025.



No. 700/CFO/Bng-East/FSR/2021

Dated: 03-01-2022

ANNEXURE - B

Group - B Educational Buildings

To,
The Authorized signatory,
M/s.Bangalore International Kids High,
No.20/A, 1st Main,
New Saptagiri Layout,
Uttarahalli Main Road,
Subramanyapura,
Bengaluru- 560 061.

Sir,

Sub: Issue of "Fire safety recommendation" to "M/s.Bangalore

International Kids High, No.20/A, 1st Main, New Sapthagiri Layout, Uttarahalli Main Road, Subramanyapura, Bangalore - 560

061"- reg.

Ref: 1) Your request letter dated: 29-11-2021

2) Report No. 11/DFO/BFS/Advice-School/2021, Dt: 22-12-2021.

<<<>>>

With reference to the subject above cited, the premises of "M/s.Bangalore International Kids High, No.20/A, 1st Main, New Sapthagiri Layout, Uttarahalli Main Road, Subramanyapura, Bangalore - 560 061." was inspected by the District Fire Office, Banashankari Fire Station, Bengaluru on 15-12-2021 with respect to Fire prevention, Fire fighting and Evacuation measures to be complied in the above premises and has submitted the details as under.

## Part-A. Details of the building / premises :-

01 Name and Address of the Applicant. The Authorized signatory,
M/s.Bangalore International Kids High,
No.20/A, 1st Main,
New Saptagiri Layout,
Uttarahalli Main Road,
Subramanyapura,
Bengaluru- 560 061.

02 Name and Address of the premises.

M/s.Bangalore International Kids High, No 20/A, 1st Main, New Saptagiri Layout, Uttarahalli Main Road, Subramanyapura, Bengaluru- 560 061.

23/13/2022

1,	to and may seeme there	We Hake it Walangth
	territary yyn ac	the Secretary,
	green to the state of the state	M/: Karsuighamsą Education Society
		i (keggi ), No. 58/7, Sabramanyapura Main
		royad, Chikkullasaridra,
		Bengaloro 4,60 001
1/1	- <b>1</b> \$9 <b>4.0336.4</b> \$195.450.9	one Building
175	Apondage of they	Basement, Ground & 3 Upper floors
η,	Harn white details of accupancy.	, <i>m</i> , s, , , , , , , , , , , , , , , ,
	Rysoment Hum	
	systate sipp	Fuditorium, Muse Class Room and
		Conference Room
		Note: The occupancy in the basement
		floor should be vacated and utilized the
		basement floor for parking purpose only.
	Gurant Hope	Entrance Tobby/ reception, pantry, I
		societacy coom, 1 conference room and 2
		class cooms
	1 theyer	6 class rooms, 1 principal's office, 1 staff
		coon and 1 store
		room and y stope
	2 then	I play area and lab room
	s" there	3 Class rooms and swimming pool.
111	Height of the building	17 90mte.
111	',014 araa	2800 (10%) mtrs.
41	Built up man of each floor	
	Bacement Hoge	435 005q mfc.
	Created floor	4.35 005q mtrs.
	1 there	4 % 00% q intro,
	J' Home	435 905g mtrs
	" &" Here	4.5.005q mtr;
117	tenal fratt apares	2,175.005q.mtrs.
11	Parrosandago properties	•
	150**	School building to the second
	11	School building belonging to the applicant Residential houses.
	110,000	
	1,0,0,0,0	10 00mtrs, wide Sapthagiri Layout road,
1 /		7.00mtrs wide Sapathagin Layout road
, ,	- 5et back area ayadable ground the bad -	ding
	Heath.	10 (Omte.
	$\int_{0}^{\infty} dx dx = \int_{0}^{\infty} dx dx$	Loomti
	Commission (Commission)	tra
	Course I was to	
	Same of 1	1 Obinti
	· West of the	

<u>Part-B</u>. On inspection of this School premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety point of view:

	ifety point of view :-				Recommendations
SI No	Details (02-)	(O3)			(04)
(1)	Accessibility to the premises	The premise is accessible from 10.00mtrs, wide Sapthagiri Layout road, located on the Northern side and 7.00mtrs, wide Sapthagiri Layout road, located on the Southern side. Both the roads are hardened to carry the weight of			The requirement is complied with
0.5	No of entrances	45.000Kgs.  Three entrances, one of 5.00mtrs, one of 4.70mtrs. and another of 1.50mtrs. width have been provided to the premises.			The requirement is complied with.
03	Width of entry / exit	Entry - 3.00mtrs. and exit 3.00mtrs. to the building.			The requirement is complied with.
04.	Diesel generators.	One diesel generator of 82.50KVA capacity has been installed.			The requirement is complied with.
05.	No. of staircases available	Nos. of staircases Width of staircases	:	01no. 1.60mtrs.	The Requirement is Complied With.
		Width of treads Height of risers	:	25cms. 15cms.	
		Nos. of riser per flight	:	13no's	
	ŧ	Height of handrails Head room	:	1.00mtrs. 2.60mtrs.	
06	No. lifts and capacity.	clearance Nos. of lifts		01 no.	The Requirement is Complied With.
00	no, mo and capacity.	Capacity of lifts	:	13 passengers.	
07	Potable Fire Extinguishers	2Nos. of ABC powder extinguishers, each of 6kgs. Capacity and 06 nos. Water pressure type extinguishers, each of 9litres capacity have been provided.			O1 ABC & CO2 Fire Extinguisher of 4Kgs Capacity for every 100.00Sq.Mtrs. of built up area of the building shall be provided.
10.	First aid Hose reel hose	Not Provided.  Not Provided. $ \begin{pmatrix} 0 & 0 & 0 \\ 0 & 0 & 0 \\ 0 & 0 & 0 \end{pmatrix} $ $ \begin{pmatrix} 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 \end{pmatrix} $ $ \begin{pmatrix} 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 \end{pmatrix} $			Hose Reel Hose of 19mm Size and of adequate length to reach the farthest point of each floor near staircase of the building shall be provided with a shut off branch having a nozzle of 5.00 mm size & the hose reel hose should be connected at each landing by means of an adaptor.

23/03/2022

11	Automatic sprinkler system	Not provided	Automatic sprinkler system with () sprinkler bulb for every 6.695(2000) should be provided at liasercery
12.	Terrace tank over respective tower terrace.	Not Provided	area The system should be concerted to, 15,000ltrs inaparity overhead tank for fire outsity compoun
13.	At the terrace tank level with minimum pressure of 3.5	Not Provided	The system should be connected a booster pump capable of derivency 9001PM
15.	Escape routes	Not provided	Direction in which the students have to move in the event of any emergency shall be indicated in the corridor on each floor during evacuation it shall be marked in luminous paint.
16	Fire order	Nat provided.	Notice boards, indicating with the details of action to be taken by the Staff/Students in case of an emergency shall be displayed cear the staircase at each floor with telephone numbers of 22971533 of Banashankari Fire Station & Central Fire Control Room i.e. 22971500, 22971600 & 101 and of cearby Ambulance Service.
17	Fire fighting training	Not Trained.	At least 40% of employees/Staff shall be got trained in basic fire fighting at our R.A. Mundkur Fire & Emergency Services Academy, Bannerghatta Road, Bangalore

Under the circumstance stated above, there is No Objection to run education activities in your school building subject to the condition of providing additional fire fighting equipments and fire precautionary measures shown in column No.4 of Part – B. Therefore, the management should comply Karnataka Fire & Emergency Services Department conditions to provide additional equipments and then intimate to this office within 90 days positively without fail. "This Fire safety recommendation Certificate valid for Only One Year from the date of issue and is renewable without fail".

All requirements recommended above are as per National Building Code-2016 Part 4 clause 3.1.3 of Fire and Life safety will have to be complied with mandatorily.



Yours faithfully

Part H